

Ho Chien PN# CA-C2059-0001

Date: 7/12/04'

Connector has to use strain relief.

Connector 1, 3 - Ribbon cable wrap over under strain relief.

Connector 2 - Ribbon cable DO NOT wrap over under strain relief. Straight through.

