Date: 10/23/04'

Connector 1: 2557-44-NX Connector 2: 2557-44-NX

44P, PIN X BLOCKED, NO BUMP, NO STRAIN RELIEF

Pin X blocked as indicated location

